



i-NOVATIVE ©

beyond tomorrow

Errata

Auto-Link-SPE-G

1000BASE-T1 Media Converter



Table of Contents

1	Revision History.....	3
2	Errata.....	3
2.1	T1 Link Speed LED.....	3
3	Support Information	3

1 Revision History

Revision	Date	Change
1.0	04/24/2021	T1 Link Speed LED Error

2 Errata

2.1 T1 Link Speed LED

The T1 Link Speed LED does not match with the speed marking on the housing.

100MBit/s are indicated with the green LED having the 1000 label.

1000MBit/s are indicated with the red LED having the 100 label.

Up to firmware revision 0.0.0.13, the green LED indicates a 100MBit/s link and the red LED indicates a 1000MBit/s link.

LED assignment is fixed in firmware revision 0.0.0.14. Beginning with this revision, the green LED labeled 1000 indicates a 1000MBit/s link, and the red LED labeled 100 indicates a 100MBit/s link.

The change is reflected in User Manual revision 1.8.

3 Support Information

i-novative[®] is a registered trademark of i-novative[®] GmbH. If you have questions concerning our product, please contact us:

Manufacturer:
i-novative[®] GmbH
Kesselbodenstrasse 11
85391 Allershausen

E-Mail: support@i-novative.de
Phone: +49 8166 5 82 91 40
Fax: +49 8166 9 88 91 70
Internet: www.i-novative.de